

02004  
502 North Allen Ave.  
Shreveport, LA 71101  
Phone: (318) 673-3802  
Fax: (318) 673-3960

# AEP ANALYTICAL CHEMISTRY SERVICES

## Analysis Report

Report ID : 17574  
Date Received: 06/12/2009  
Company: AEP-TXC - Central Division (LD)  
Contact: Larry Dombusch  
Phone: (361) 242-3606  
Address: 3601 Callicote Road  
Corpus Christi, TX 78410

Customer SampleID	Parameter	Value	Unit	DLm	DIC	Method	Matrix	Serial #	Type	Man. Equip	Size	Sample Description	Location	Collected By	Collected Date	Analysis Date	Tech
123078	PCB-OI	<1	mg/kg	1	1	8082	Oil	#2 Blue Tank	A					JC	6/8/2009	6/28/2009	SW
123079	PCB-OI	<1	mg/kg	1	1	8082	Oil	#1 Blue Tank	A					JC	6/8/2009	6/28/2009	SW
123080	PCB-OI	<1	mg/kg	1	1	8082	Oil							JC	6/8/2009	6/28/2009	SW
123081	PCB-OI	<1	mg/kg	1	1	8082	Oil							JC	6/8/2009	6/28/2009	SW

### Quality Control Data

Date	Parameter	Sample ID	Blank Value	Standard		Spike Recovery %	Surrogate % Recovery	Duplicates Difference	Tech
				Value	Recovery				
6/28/2009	PCB-Aroclor 1242	124522	<1	50	50	107.2	90.0	0.0	SW
6/30/2009	PCB-Aroclor 1242	124021	<1	50	59.3	102.9	106.0	0.0	SW
6/28/2009	PCB-Aroclor 1254	124070	<1	50	54.4	56.4	92.0	0.0	SW
6/28/2009	PCB-Aroclor 1254	123982	<1	50	54.4	114.3	92.0	0.0	SW
6/28/2009	PCB-Aroclor 1260	124016	<1	50	45.2	104.0	104.0	0.0	SW
6/30/2009	PCB-Aroclor 1260	124062	<1	50	44.8	94.0	94.0	0.0	SW
6/28/2009	PCB-OI	123973	<1	50	44.8	94.0	94.0	0.0	SW
6/29/2009	PCB-OI		<1	50	44.8	94.0	94.0	0.0	SW
6/29/2009	PCB-OI		<1	50	44.8	94.0	94.0	0.0	SW
6/30/2009	PCB-OI		<1	50	44.8	94.0	94.0	0.0	SW

Sample 113318 was all water and could not be analyzed. Please send 1 Liter (1000 ml) for water analysis.

*Larry Dombusch*  
Laboratory Manager

Tuesday, June 30, 2009  
Report Date